

Test Report issued under the responsibility of :

DEKRA Certification B.V.





Meander 1051, 6825 MJ Arnhem, The Netherlands

T +31 88 96 83022

F +31 88 96 83100

[www.dekra-certification.com](http://www.dekra-certification.com)

<b>TEST REPORT</b>	
<b>Report Reference No.</b> .....	2199622.50
<b>Tested by (name + signature)</b> .....	J.G.H. Gelink 
<b>Approved by (name + signature)</b> .....	H.J.H. te Lindert 
<b>Date of issue</b> .....	04-01-2017
<b>Contents / enclosures</b> .....	21
<b>Testing Laboratory</b> .....	DEKRA Certification B.V.
<b>Testing location / address</b> .....	Meander 1051, 6825 MJ Arnhem, The Netherlands
<b>Applicant</b> .....	Global Technics Medicare B.V.
<b>Address</b> .....	Bargelaan 6, 2333 CT Leiden , The Netherlands
<b>Test specification:</b>	
<b>Standard(s)</b> .....	IEC 60598-1, IEC 60335-1, IEC 61439-5, IEC 60529, IEC 60068-2-11, IEC 62262/EN 50102
<b>Test procedure</b> .....	Safety test <input checked="" type="checkbox"/> Screen test <input type="checkbox"/> Quick scan <input type="checkbox"/> Performance test <input checked="" type="checkbox"/> Flash test <input type="checkbox"/> IP test <input checked="" type="checkbox"/>
<b>Test object description</b> .....	
Trade Mark.....	Global Technics Medicare
Manufacturer .....	Global Technics Medicare B.V.
Model/Type reference .....	Sixcase
Ratings .....	100 – 240 V, 50/60 Hz, 2 A, class II (ratings AC/DC adapter), IP54, Tambient is till – 15 °C.
<b>Number of test objects</b> .....	1
<b>Possible test case verdicts:</b>	
- test case does not apply to the test object...:	N/A
- test case is not checked to the test object...:	N/C
- test object does meet the requirement.....:	P(Pass)
- test object does not meet the requirement...:	F(Fail)
<b>Test program</b> .....:	The test object has been submitted to a test program as mentioned on the next page.
<b>Summary of test results:</b>	
-	All test are passed with positive results
<b>The test results shown in this report relate only to the tests performed according to the test program. The test object has not been submitted to a full test program.</b>	
© Integral publication of this document is allowed.	